

ProTection Plan


Maximum uptime,
minimum cost

We get it – accidents happen. Don't let repairs slow you down or cost you thousands of dollars. For accidental repairs not covered by our limited warranty, get worry-free hardware coverage with ProTection Plan.

SAVE
\$2,500+
ON REPAIRS



ProTection Plans (1 year)




Pro95 S or Pro55 S
[SRI-0802004]
\$1,315



Pro Wash/Dry
[SRI-0802005]
\$425



ProCure 2
[SRI-0802010]
\$425



Bundle
Printer, Wash/Dry, ProCure 2 [SRI-0802008]
\$1,925

- ProTection Plan is available for your whole SprintRay ecosystem or individual products.
- Don't miss out on savings. For newly purchased hardware, ProTection Plan is only available to buy during the 30 days after purchasing.
- If your SprintRay product isn't functioning correctly, we'll send you a replacement immediately, free of charge. Once you receive it, send us back your malfunctioning unit.
- ProTection Plan will cover the cost of your first claim and provide a discount for each repair after that.

Repair Costs with ProTection

1st Claim	FREE
2nd Claim	50% discount on Tier repair cost
3rd Claim	25% discount on Tier repair cost

Repair Costs with ProTection (after 1st Claim)

Tier 1	\$375
Tier 2	\$500
Tier 3	\$750
Tier 4	\$1,500+*


Repair Costs without ProTection

Tier 1	\$750
Tier	\$1,000
Tier 3	\$1,500
Tier 4	\$2,500+

Purchase ProTection Plan Today

Contact your SprintRay sales representative to purchase ProTection Plan or contact customer support at support@sprintray.com

Repair costs without ProProtection Plan



Printers



ProCure 2



ProWash

Tier 1

SRI-0804011

\$750

- Loose Cable
- Firmware Update

- Simple Repair

- Firmware Update
- Splash Guard Replacement
- Reservoir Lid Replacement

Tier 2

SRI-0804012

\$1,000

- Front Panel Replacement
- Red Hood Replacement
- LCD Board Replacement

- Moderate Repair

- Pump Replacement
- Reservoir Replacement
- Motherboard Replacement

Tier 3

SRI-0804013

\$1,500

- Screen Replacement
- Motherboard w/ Computer Replacement
- Pro95 Metal Plate Bottom Shell
- *Resin Clean-up Only

- Advanced Repair

- All Other

Tier 4

SRI-0804012

\$2,500+*

- Projector Replacement
- Projector Lens Replacement
- *Resin Clean-up Plus Hood, LCD, Screen, Front Panel
- **Resin Clean-up Plus Projector

- All Other

- All Other